



Sydney
 0416040076
 mobileauto@bigpond.com
 mobileautomotivesolutions.com.au

Mobile Automotive Solutions PTY LTD

Tax Invoice

Bill To: Will Davies
 Will@carnextdoor.com.au, kristine@carnextdoor.com.au

Invoice No: APP4459
Date: 09/05/2024
Due Date: 09/05/2024

REGO: CY91UU **YEAR:** 2010
MAKE: Hyundai **ODO:** 232255
MODEL: Iload

Description	Quantity	Rate	Amount
5w40 Ultra Full syn engine oil	7.5	\$21.00	\$157.50
Oil filter (large diesel)	1	\$46.00	\$46.00
Air filter element	1	\$50.00	\$50.00
Workshop consumables, solvents, sundries and waste oil disposal.	1	\$15.00	\$15.00
Labour on service: -Check all the lights. -Clean the air filter, when can. -Check or top up fluids. -Adjustments where needed. -Tighten bolts where needed. -Check Tyre pressures. -Visual inspection. -Test drive. Check the Wheel speed sensor with a multimeter for open circuit.	1.5	\$118.18	\$177.27
Diagnostic scan, clear fault codes. For fault codes refer to attachments.	1	\$90.91	\$90.91

Payment Details

Mobile Automotive Solutions PTY LTD
BSB: 032159 ACC: 376786

ABN: 35168714029

Subtotal	\$536.68
GST 10%	\$53.67
Total	\$590.35
PAID	\$0.00

Balance Due \$590.35

Notes

At the next service or sooner:

There is oil leaks in various places. Most of the oil is coming out of the split intercooler.

The intercooler and the right rear wheel speed sensor needs to be replaced.




Photo 1

